10

0039102

START

Department of Energy

Richland Operations Office P.O. Box 550 Richland, Washington 99352 NOV 0.4 1094

95-PCA-029

Mr. Randall F. Smith, Director Hazardous Waste Division U.S. Environmental Protection Agency Region 10 1200 Sixth Avenue Seattle, Washington, 98101

Ms. Dru Butler, Program Manager Nuclear Waste Program State of Washington Department of Ecology P.O. Box 47600 Olympia, Washington 98504



Dear Mr. Smith and Ms. Butler:

HANFORD FACILITY DANGEROUS WASTE PART A PERMIT APPLICATION, FORM 3, REVISION 4, FOR THE 218-E-8 BORROW PIT DEMOLITION SITE (WA7890008967) (TSD: T-2-1)

Enclosed is the Hanford Facility Dangerous Waste Part A Permit Application (Part A), Form 3, Revision 4, for the 218-E-8 Borrow Pit Demolition Site (218-E-8 Borrow Pit). The 218-E-8 Borrow Pit is located in the 200 East Area of the Hanford Facility and was used for the detonation of explosive waste that is generated on the Hanford Facility. This Part A, Form 3, was revised to incorporate information detailed in the 218-E-8 Borrow Pit Demolition Site Closure Plan that was submitted to the State of Washington Department of Ecology and the U.S. Environmental Protection Agency on October 21, 1994.

The 218-E-8 Borrow Pit Part A, Form 3, has been revised to modify the following dangerous waste numbers: 1) delete Dangerous Waste Numbers D002 (corrosivity), D035 (toxicity - Methyl ethyl ketone), U098 (1,1-Dimethylhydrazine), U159 (Methyl ethyl ketone), and State-only Dangerous Waste Number WC01 (extremely hazardous waste - carcinogenic); and 2) add Dangerous Waste Number U160 (Methyl ethyl ketone peroxide) and State-only Dangerous Waste Number WC02 (dangerous waste - carcinogenic). These changes to the Part A, Form 3, were made in compliance with Washington Administrative Code (WAC) 173-303. This regulation requires submittal of a revised Part A, Form 3, that accurately reflects the dangerous waste to be treated, stored, and/or disposed of at a treatment, storage, and/or disposal unit.

Should you have any questions regarding the 218-E-8 Borrow Pit Part A, Form 3, please contact Mr. C. E. Clark, U.S. Department of Energy, Richland Operations Office, on (509) 376-9333 or Mr. R. C. Bowman, Westinghouse Hanford Company, on (509) 376-4876.

Sincerely,

Robert S. Holt/for

· 有,概则的 解血 。

James D. Bauer, Program Manager Office of Environmental Assurance, Permits, and Policy DOE Richland Operations Office

EAP: EMM

William T. Dixon, Manager Environmental Services

Westinghouse Hanford Company

Enclosure:

Hanford Facility Dangerous Waste Part A Permit Application, Form 3, Revision 2, for the 218-E-8 Borrow Pit

cc w/encl:

Administrative Records, H6-08

- R. Bowman, WHC
- D. Duncan, EPA
- F. Ma, Ecology

cc w/o encl:

- B. Burke, CTUIR
- W. Dixon, WHC
- R. Jim, YIN
- D. Lundstrom, Ecology
- D. Nylander, Ecology
- D. Powaukee, NPT
- S. Price, WHC
- D. Sherwood, Ecology

ENCLOSURE

I have been to be the me on as

218-E-8 Borrow Pit Demolition Site Rev. 4, 11/04/94, Page 1 of 7

Please print or type in the unshaded areas only (fill-in areas are spaced for elite type, i.e., 12 character/inch).

FC	RM	Т				<u> </u>											1. EPA/	STATE I.). NU	MBEF			
	3 DANGEROUS WASTE PERMIT APPLICATION WA 7 8 8 0 0 0 8 9 6 9 6 9 6 9 6 9 6 9 6 9 6 9 6 9 6 9														6 7								
	OR OFFICIAL USE ONLY APPLICATION DATE RECEIVED COMMENTS																						
API	PLIC. PPRO	TA JVC	ION ED	DATE RECEIVED (mo.,day,& yr.)											CO	MMENTS							
11.	II. FIRST OR REVISED APPLICATION																						
appl	lace an "X" in the appropriate box in A or B below (mark one box only) to indicate whether this is the first application you are submitting for your facility or a revised application. If this is your first application and you already know your facility's EPA/STATE I.D. Number, or if this is a revised application, enter your facility's EPA/STATE I.D. Number in Section I above.																						
A.	FIRS	7		ICATION (place an		•		-															
	١	Ц	1.	EXISTING FACILITY		uctions for defii item below.)	ritio.	n of "c	existi	ng" f	acili	ty.				2. NEW FAC	ILITY (Co	mplete ite	m be	low)			
		0	~~~	1	OPERATIO	TING FACILITIES IN BEGAN OR T Oxes to the left!	, PF 1E (OVIDI DATE (THE CONS	E DAT	TE //	no., d N CO	ву. ММ	& EN	CEC	MO. DAY		FOR NEW PROVIDE 1 (mo., day,	THE D	ATE,	•		
		<u> </u>			•		_											TION BEGA					
В.	REVISED APPLICATION (place an "X" below and complete Section I above) [X] 1. FACILITY HAS AN INTERIM STATUS PERMIT [2. FACILITY HAS A FINAL PERMIT																						
10.	PRO	CE	SSE	S - CODES AND CA	PACITIES																		
٠ (ode	8.	If m	ODE - Enter the code ore lines are needed luding its design cap	, enter the	code(s) in the	spac	e pro	⁄ided	. If a	я рго	Cess '	es e will	ac be	h pr use	rocess to be used at the fac d that is not included in the	lity. Ten list of co	lines are des below	provi	ded fo n des	r enti cribe	ering the	
B. F	ROC	CES	ss D	ESIGN CAPACITY - I	For each o	ode entered in o	olu	mn A	enter	the c	сара	city o	f the	ері	roce	966,							
1	. AI	мо	UNT	- Enter the amount.								-											
2	. UN	ΝIΤ	OF	MEASURE - For each	amount	entered in colum	n B	(1), an	ter ti	he co	de f	rom tl	he li	st c	of u	nit measure codes below the	at describ	es the un	it of (measu	re us	od.	
	Or	nly	the	units of measure tha	it are liste PRO-	d below should APPROPRIAT)F								PRO-	APPR	OPRIA	ATF 11	NITS	OF.	
_				ROCESS	CESS CODE	MEASURE FO	R P	ROCE	SS 					_		PROCESS	CESS	MEAS	URE I	FOR F	ROCE	SS	
	Stora	-														ment:							
7	ANI	ĸ		(barrel, drum, etc)	S01 S02	GALLONS OR I							ANK		TO1 GALLONS PER DAY OR LITERS PER DAY								
			PILI		\$03 \$04	CUBIC YARDS								ACE IMPOUNDMENT	TO2 GALLONS PER DAY OR LITERS PER DAY TO3 TONS PER HOUR OR								
	ouk: Dispo			MPOUNDMENT	S04	GALLONS OR I	RS						11/4	ICIN	IERATOR	TO3 TONS PER HOUR OR METRIC TONS PER HOUR; GALLONS PER HOUR OR							
1				WELL	D80	GALLONS OR	.ITE	RS				LITERS PER HOUR											
ŀ	.ANI	DFI	LL		D81	ACRE-FEET (th would cover or	0 8				OTHER (Use for physical, chemical, TO4 GALLONS PER DAY OR thermal or biological treatment LITERS PER DAY												
						depth of one for OR HECTARE-I	AET!							ŝ١	urfac	esses not occurring in tanks, ce impoundments or inciner-							
				ICATION POSAL	D82 D83	ACRES OR HEG GALLONS PER	DA'				ators. Describe the processes in the space provided; Section III-C.)												
	UR	FAC	CE IN	APOUNDMENT	D84	LITERS PER DA GALLONS OR I		RS															
					UNIT OF MEASUR											NIT OF ASURE				UNIT			
-				ASURE	CODE	_	UNIT								CODE UNI	IT OF MEASURE CODE				DE			
l	ITE!	RS.				3 L		LITER	PER	HOU	к.,					,,, D HEC	JIAKE-M	ETER				. F	
	CUBI		METI	DS ERS ER DAY		r C		GALL	ONS	PER I	HOU.	Я				W ACI	RES CTARÉS.		· · · ·	: : : :		. a	
<u>`</u>	ML		13 F	EXAMPLE FOR CO	MPLETING	SECTION III (s	ow	n in lit	o nu	mber	s X-	1 and	X-2	be	low	d: A facility has two storag	e tanks, i	one tank d	an				
	Т			hold 200 gallons a	nd the oti	i <i>er cen hold 400</i> IGN CAPACITY	gai	lons.	The	facilit	ty ale	so has	an	inc	cine	rator that can burn up to 20 B. PROCESS D	gallons p	per hour.					
Ļυ		ΈS	S [D. MO	JEGG BEG	- I GIT CALACITY	2.	UNIT	1 ,	FOR FFICI		լլ Մ	A.	PF ES:	₹0- \$	B. PROCESS D	LOIGIN CA	RPACITY	2.	UNIT		OR	
N B	(fre		list		AMOUNT		١ ٤	MEA-	[USE		I M N B	(fro		list	1. AMOUI			OF	MEA- JRE	, ,	FICIAL JSE NLY	
E E	at	bov	(e)		.,,,,,,,			enter eode)				E E	al	ov	(specify)					nter de)	ľ		
X-1	s	o	2		600			G	T	<u> </u>	T	Б							1		T		
X-2	7	o	3		20		E				6						<u> </u>		\top	+	1-1-		
1	T	0	4		150			U				7											
2	Ц	_			- , .		_	Ц.			_	8			Ц								
3		_					_				_	9											
4							L					10											

the fact of the man in the Com-

218-E-8 Borrow Pit Demolition Site Rev. 4, 11/04/94, Page 2 of 7

Continued from the front.

III. PROCESSES (continued)

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESS (code "TO4"). FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY,

T04

The 218-E-8 Borrow Pit is located in the 200 East Area of the Hanford Facility. (The 218-E-8 Demolition Site occupied only a small portion, an area 6 meters (20 feet) by 6 meters (20 feet), of the larger 218-E-8 Borrow Pit. The 218-E-8 Demolition Site was used to detonate explosive discarded chemical products used on the Hanford Site. The process design capacity for treatment at the 218-E-8 Demolition Site was 150 gallons (568 liters) per day.

IV. DESCRIPTION OF DANGEROUS WASTES

- A. DANGEROUS WASTE NUMBER Enter the four digit number from Chapter 173-303 WAC for each listed dangerous waste you will handle. If you handle dangerous wastes which are not listed in Chapter 173-303 WAC, enter the four digit number(s) that describes the characteristics and/or the toxic contaminants of those dangerous wastes.
- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE CODE
POUNDS		KILOGRAMS

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

D. PROCESSES

1. PROCESS CODES:

For listed dangerous waste: For each listed dangerous waste entered in column A select the code(s) from the list of process codes contained in Section III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed dangerous wastes: For each characteristic or toxic contaminant entered in Column A, select the code(s) from the list of process codes contained in Section III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed dangerous wastes that possess that characteristic or toxic contaminant.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: DANGEROUS WASTES DESCRIBED BY MORE THAN ONE DANGEROUS WASTE NUMBER - Dangerous wastes that can be described by more than one Waste Number shall be described on the form as follows:

- Select one of the Dangerous Waste Numbers and enter it in column A. On the same line complete columns B, C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- 2. In column A of the next line enter the other Dangerous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
- 3. Repeat step 2 for each other Dangerous Waste Number that can be used to describe the dangerous waste.

EXAMPLE FOR COMPLETING SECTION IV Ishown in line numbers X-1, X-2, X-3, and X-4 below! - A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

	T							D. PROCESSES										
	A. DANGEROU WASTE NO			RC E N	٥.	B. ESTIMATED ANNUA QUANTITY OF WASTE	C. UNIT OF MEA- SURE (enter code)	۱۰	1	I. P		SS	COD	ES			2. PROCESS DESCRIPTION (if a code is not entered in D(1))	
X-1	7	<u> </u>	0	Б	4	900	Р	7	T 0 3	D	8 0		T		Τ.	Τ		
X-2	ı	7	0	0	2	400	Р		т о з	D	8 O	Γ	777		7	Τ		
X-3	. [2	0	0	1	100	• Р		7 0 3	٦	8 0	_	T			Т		
X-4	1	9	o	0	2				т о з	D	8 0	Γ	T		1	T	included with above	

218-E-8 Borrow Pit Demolition Site Rev. 4, 11/04/94, Page 3 of 7

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

I.D.	NUN	/BE	R /	ente	this page before completing red from page 1)	, , , , , , , , , , , , , , , , , , , ,						10 //3	<u> </u>				
W A 7 8 9 0 0 0 8 9 6 7																	
IV.	V. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES																
L NO	1	A. DANGEROUS B. ESTIMATED ANNUAL QUANTITY OF WASTE (enter code)			L E	(en	UNIT MEA- IRE Iter de)			1. F	PROCE (en	SS (CODE	S		2. PROCESS DESCRIPTION (if a code is not entered in D(1))	
1	Д	0	0	1	1,000		K		T	04		1	-			7	Treatment-Other (Demolition)
2	D	0	0	3			+			<u>'</u>	<u> </u>		' 	· ·	'	· 	
_	U	一	7	_			+	-		1	-			- -		1	
	U	-+	+	\dashv			_			1	 	- 1			1		
	W	一					+	-		-			-		 	<u> </u>	
	W	7	寸	寸			-			,		1		<u></u>	1	1	Included with above.
8	"	•	٦	-			- '	!	!	1		Τ-		1	1	-	included with above.
9	$ \cdot $	_	_	+			+		7-	Т	-	1	-	T	Т	Τ.	
10							-	 -	 	Т		I		Т	1	Γ-	
11									Г	T	1	Ī			Т	ı	
12									1						ı	1 -	
13	 								1	.,			[1	
14		_	_				_	_			<u> </u>		_	 		·	
15								\perp	' 	· 		-	' 	' '		<u>'</u>	
16		_		_			_ -	_	, 	· 	'	<u>'</u>		· ·	·	· -	
17		1					\downarrow	+			-		-		-	-	
18	H	\dashv		4			$\frac{1}{1}$	-		Τ	-	- 1	-		 T	T	
20	-		-	\dashv			+	+	-	—	+	<u> </u>	-	" [-	1	
21	H	_	\dashv	\dashv			+	-		1	-	-1	-	<u> </u>	-	<u> </u>	
22	\parallel	-	_	+	 		+	+	-	1	 	<u> </u>	+-	1	1	1	
23		-		+			-		Т	Τ		-	¬		T	\top	
24				1					T	Т		- -		· ·	T	1	
25												1	_			T	
26										<u> </u>						7	
_					FCY 030-31 Form 3						PAGE			OF 5			CONTINUE ON DEVERSE

The second of the second of

Continued from the front,		
IV. DESCRIPTION OF DANGEROUS WASTES (continued)		
E. USE THIS SPACE TO LIST ADDITIONAL PROCESS CODE	FROM SECTION D(1) ON PAGE 3.	
explosive chemical waste. The wignitability (D001) and reactivi chemical products (U108 or U160) might have the state-only design waste (WT02) and carcinogenic dawaste of 1,000 kilograms (2,205	used for treatment of shock-sensity aste exhibited the dangerous waste ty (D003). Some compounds were known Depending on the nature of the vations for toxic extremely hazardoungerous waste (WCO2). The estimate pounds) represents the total amount eated at the 218-E-8 Demolition Sit	characteristics of own to be discarded waste treated, the waste us (WTO1) or dangerous ed annual quantity of tof dangerous waste
		'
V, FACILITY DRAWING		
All existing facilities must include in the space provided on pa	ige 5 a scale drawing of the facility (see instructions for more of	detail).
VI. PHOTOGRAPHS		
All existing facilities must include photographs <i>laerial or grou</i> , sites of future storage, treatment or disposal areas <i>(see instr</i> i	nd-level) that clearly delineate all existing structures; existing st actions for more detail).	torage, treatment and disposal areas; and
	information is provided on the attached	
LATITUDE (degrees, minutes, & second		rees, minutes, & seconds)
VIII. SACILITY OWNED		
VIII. FACILITY OWNER		
A. If the facility owner is also the facility operator as liste below.	d in Section VII on Form 1, "General Information", place an "X"	in the box to the left and skip to Section IX
D. Make desillar comments and the desillar	Lie Constant VIII of Fig. 4	
B. If the facility owner is not the facility operator as listed	in Section vii on Form 1, complete the following items:	
1. NAME OF F	ACILITY'S LEGAL OWNER	2. PHONE NO. (area code & no.)
0.077677.00.00.004		
3. STREET OR P.O. BOX	4. CITY OR TOWN	5. ST. 6. ZIP CODE
111111111111111		
IX. OWNER CERTIFICATION		
certify under penalty of law that I have personally examined nquiry of those individuals immediately responsible for obtaini here are significant penalties for submitting false information,	and am familiar with the information submitted in this and all at ng the information, I believe that the submitted information is to including the possibility of fine and imprisonment.	ttached documents, and that based on my rue, accurate, and complete. I am aware that
NAME (print or type)	SIGNATURE 1	DATE SIGNED .
John D. Wagoner, Manager J.S. Department of Energy	$(\downarrow V I) [I]_{*}$	11/61
Richland Operations Office	John D. Vagoni	1114144
X. OPERATOR CERTIFICATION		
certify under penalty of law that I have personally examined nquiry of those individuals immediately responsible for obtaini	and am familiar with the information submitted in this and all at no the information, I believe that the submitted information is to including the possibility of fine and imprisonment.	ttached documents, and that based on my
· · · · · · · · · · · · · · · · · · ·		
NAME (print or type)	SIGNATURE	DATE SIGNED
SEE ATTACHMENT		
· · · · · · · · · · · · · · · · · · ·		•

I have been a 218-E-8 Borrow Pit Demolition Site Rev. 4, 11/04/94, Page 5 of 7


X. OPERATOR CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

John D. Wagoner, Manager U. S. Department of Energy Richland Operations Office

a. Lamas Trego A. LaMar Trego, President Westinghouse Hanford Company

218-E-8 Borrow Pit Demolition Site Site Plan



218-E-8 Borrow Pit Demolition Site Rev. 4, 11/04/94, Page 6 of 7

218-E-8 BORROW PIT DEMOLITION SITE



46°33'47" 119°31'05"

94090243-12CN (PHOTO TAKEN 1992)